

## International Islamic University Chittagong

Kumira, Sitakunda, Chittagong-4318

City Liaison Office: 154/A, College Road, Chittagong-4203

Tel: 031-610085, 610308, 638657, Fax: 031-610307, Ext: 123/150


Website: [iiuc.ac.bd](http://iiuc.ac.bd)

Date: 12 March 2017

### Re-TENDER NOTICE

Sealed quotations are hereby invited from the genuine firms/suppliers for supplying **Thumb Impression Machine at Kumira, Sitakunda, Chittagong** with the following terms and conditions:

1. Participant firms/suppliers are advised to quote the rate in their official pad **Thumb Impression Machine** must be mentioned on the Envelop.
2. Tender documents & other details are available at Accounts & Finance Division (ACFD) of IIUC and may be procured paying Tk-200/- (Two hundred taka only) within office time. Tender Schedule may also be downloaded from the web site ([www.iiuc.ac.bd](http://www.iiuc.ac.bd)). Money receipt must be enclosed with the quotation in both cases.
3. Quotations are to be dropped on or before **19 March 2017** before **11.00 am** in the tender box kept in the office of the Chairman, Purchase & Procurement Committee, City Liaison Office (2nd Floor), Chawkbazar, Chittagong. Tender Box shall be opened on the same day in presence of participants or their representatives (if any).
4. The authority of IIUC preserves the right to accept or reject all quotations either partly or in full and is not bound to accept the lowest quotation without giving any reason what's ever.
5. Suppliers shall have to deliver the goods by their own cost/arrangement to the specified place.
6. Quotations are to be dropped with 2.5% earnest money in the form of **Pay Order** favoring IIUC from IBBL or any scheduled bank.
7. Bill may be paid after taking delivery, deducting VAT/AIT as per government rules & performing other official formalities. If any default is found, payment will be suspended till the defaults are removed.
8. For any details or clarifications interested bidder may contact IT Division, Tel: (03042) 51154-60 Ext- 320 & 321 (Cell: 01711196626).

 12.03.2017

**Mahmudul Alam**  
Director (in-charge)  
Purchase & Procurement Division (PPD)  
International Islamic University Chittagong

# International Islamic University Chittagong

## Specification & Location for Thumb Impression Machine

- **Thumb Impression Machine Specification:**

1. Each Machine Should be equipped to enroll 5000+ attendees.
2. Human to Machine Interface: Machine should be equipped with a display to show Photo ID during in Log-in & Log-out with an interactive sound/ LED indications.
3. Machine should be equipped to store 50000+ LOG (Employees in and out information).
4. Operation Mode Support: Card+ fingerprint.
5. Machine should be equipped with Optical Sensor for Finger Print and Pulse Sensing or tools to detect fake thumb.
6. USB Support for Data Transfer facility in Machine (Optional)
7. Back-End Database support: MYSQL/MSSQL Server 2008 R2
8. In the client-server framework, associate software should have built-in report template and software module for HR Management in which IIUC can incorporate its HR policy without any third party involvement.
9. For physical security these machines should be installed inside a customized lock-up box. Hence these customized lock-up box needed to be procured and fitted at the entrance of the each building.
10. Each TCP/IP based machine needs to have PoE (Power over Ethernet) support. In order to connect all the machines to the IIUC Computer Network, the following network devices and accessories are also required.

Devices	Quantity
8 Port PoE Switch	08
Cabling Channel, UTP Cables	As required

- **Location:**

At least 8 Machines will be required to connect all the building of IIUC in which 7 will be installed in the following 7 buildings and rest 1 machine will be kept at ITD as a secondary device for troubleshooting.

Location	No. of Machine
Central Library Building	01
Law Dept. Building	01
Academic Building # 2	01
FSE Building	01
DBA Building	01
Academic Building # 4	01
Administrative Building	01
Stock for Troubleshooting (ITD)	01